

Truth in Sale of Housing Disclosure Report

NOTICE - Read Entire Report Carefully. This is not a Buyer's Inspection!

Address: 4937 6th St N Minneapolis, MN



Current Owner Name: Wachovia Mortgage c/oSteve Mikula

Contact: Wachovia Mortgage c/oSteve Mikula

Business/Relationship:

Owner Address: 11660 Theater Dr N #110
Champlin, MN 55316

Work/Business: 952-212-9388

I declare to the best of my knowledge the following information:

This property has had environmental testing, removal, or remediation of environmental contamination by the United States Environmental Protection Agency, Minnesota Pollution Control Agency, other governmental agency, or under the direction of such agency: Yes / No

If yes, the seller shall provide the testing, removal, or remediation results to the buyer.

Water Damage to Property: flood damage sewer backup water seepage

Please Describe:

Age of Roof: _____ **Condition of Roof:** Poor Fair Good Excellent **Currently Leaking:** Yes / No **Patched:** Yes / No

Signature of Owner: (Report Not Valid Without Signature)

Date:

***** SEE ATTACHED PAGES FOR IMPORTANT CONSUMER INFORMATION *****

THERE ARE REQUIRED REPAIR/REPLACE ITEMS NOTED IN THIS REPORT.

Observed Number of Units: 1

City Reference as: 1

Building Type: Single Family Home

Present Occupancy: Conforming

Zoning: R1A - Single Family District(`99)

Housing Orders: No

Condemnation Status: NA

Reason: NA

1. This report offers a limited overview of the building components and fixtures and is not technically extensive. Prospective buyers may want to seek additional opinions from various experts in the inspections field prior to purchase. This report is not a warranty or guarantee, expressed or implied, by the City of Minneapolis or by the evaluator or of any building component or fixture. Further, the buyer may want to seek additional information regarding any open permits. For 1st time condominium units, this report includes only those items located within the residential units. The Professional Opinion covers those items in the common areas of the building.
2. The buyer must repair all items marked Repair/Replace, unless the seller agrees to do the repairs. The seller is not required to complete the RR's if the property does not sell. All required Repair/Replace items are enforceable by Minneapolis Ordinance Chapter 248 and/or 250. All other items will not be used by the Inspections Division as a basis for enforcing Minneapolis ordinances.
3. The ordinance requires that no person shall exhibit or show a dwelling for sale without first having obtained an official Evaluation Report and places the responsibility on the seller or agent to make sure that this report (and in the case of 1st time condo conversions, the Professional Opinion,) is publicly displayed on the premises at all times when the house is shown to prospective buyers. Also, the seller or agent must give a copy of this report (and Professional Opinion for 1st time condo conversions) to the buyer prior to the signing of a Purchase Agreement, or as otherwise required in Minneapolis Ordinance Chapter 248 and/or 250.
4. This report covers only those items listed on the form. The evaluator is not required to ignite the heating plant, use a ladder to observe the condition of the roofing, evaluate inaccessible or concealed areas or disassemble items. This report does not address formaldehyde, lead paint, any airborne gasses (including radon), asbestos, wood stoves, fireplaces or air conditioners. Gas inserts in fireplaces WILL be evaluated.
5. This report is not an FHA, VA or Section 8 inspection. This report is not a code compliance inspection. It is not an appraisal. This report may be based upon different standards than the lender, FHA or VA.
6. The seller is required to provide the disclosure information in the box above. If this is not filled out, buyers are advised to request the seller to do so.
7. This report is valid for two years from the date of issue and only for the owner named on the report. It is required for all single-family homes, duplexes, townhouses or 1st time condominium conversions offered for sale.
8. **Any questions** regarding this report should be directed to the evaluator whose name and phone number appear below.
Any complaints regarding this report should be directed to Truth in Housing at (612) 673-5840, Minneapolis Inspections Division, 250 South 4th Street #300, Minneapolis, MN 55415.

I hereby certify that this report is made in compliance with the Minneapolis Code of Ordinances, Chapter 248, and that I utilized care and diligence reasonable and ordinary for one meeting the Certification Standards. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrant future useful life of any house component or fixture. I have included all required information pages with this report.

Evaluator Name: Ron Kulas

Phone: 651-641-0641

Evaluation Date: 3/27/2010

Signature: Ron Kulas

Evaluation #: 20101951

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements **C** :=Comments **NA** :=Not Applicable/Does Not Apply **B** :=Below Minimum Requirements **SC** :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required **RRP** :=Repair/Replace, Permit/City Inspector Required **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Basement

1. Basement Stairs/Railings
M, Meets Minimum Requirements
2. Basement Floors
M, Meets Minimum Requirements
3. Foundation Walls
M, Meets Minimum Requirements
4. Evidence of Dampness or Staining
C, Other Comment: - Evidence of past dampness and/or staining. (C)
5. First Floor, Floor System
M, Meets Minimum Requirements
6. Columns & Beams
M, Meets Minimum Requirements
7. Basement Sleeping Rooms
C, Other Comment: - Yes, there are basement bedrooms. See Bedroom Section for details. (C)
8. Basement Plumbing Fixtures
M, Meets Minimum Requirements
9. Sump Pumps
RRE, Repair/Replace: - Loose cover on sump pump. (RRE)
10. Smoke Detectors / CO Detectors
RRE, Repair/Replace: - Does not respond when tested. (RRE)
11. Basement Electrical Outlets/Fixtures
M, Meets Minimum Requirements

Electric

Amps: 100

Volts: 115/230

12. Electrical service installation
M, Meets Minimum Requirements
13. Separate 20-amp Kitchen Circuit indexed at Service Panel
M, Meets Minimum Requirements
14. Separate 20-amp Laundry Circuit indexed at Service Panel
M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Plumbing

- 15. Floor Drains
M, Meets Minimum Requirements
- 16. Drain, Waste & Vent Piping
RRE, Repair/Replace: - Water off at time of evaluation. Re-inspection required. (RRE)
- 17. Water Supply Piping
RRE, Repair/Replace: - Water off at time of evaluation. No other visible problems. Evaluator required to return after water service restored. (RRE)
- 18. Gas Piping
M, Meets Minimum Requirements
- 19. Copper Water Line Visible on the Street Side of Water Meter
M, Meets Minimum Requirements

Water heater

- 20. Water Heater & Installation
RRE, Repair/Replace: - Missing/improper T&P relief valve discharge pipe. Pipe must be full sized, of proper metal materials, not capped, must extend to within 18" of the floor, with no threads on end of the pipe. (RRE)
- 21. Water Heater Venting
RRE, Repair/Replace: - Water heater venting not viewed in operation. Reinspection required (RRE)

Heating

HeatingFuel: Gas

HeatingType: Forced air

- 22. Heating Plant Viewed in Operation
RRE, Repair/Replace: - Heating plant not in operation. Reinspection required. (RRE)
- 23. Heating Plant & Installation
M, Meets Minimum Requirements
- 24. Heating Plant Combustion Venting
M, Meets Minimum Requirements
- 25. Incinerator / Abandoned Oil Tanks / Misc Gas Fixtures
NA, Not Applicable/Does Not Apply

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Laundry

26. Gas Piping

M, Meets Minimum Requirements

27. Dryer Venting

M, Meets Minimum Requirements

28. Plumbing Fixtures

RRE, Repair/Replace: - Water off at time of evaluation. No other visible problems. Evaluator required to return after water service restored. (RRE)

Kitchen

29. Walls and Ceiling Components

B, Below Minimum Requirements: - Damaged wall/ceiling. (B)

30. Evidence of Dampness or Staining

M, Meets Minimum Requirements

31. Floor Condition

M, Meets Minimum Requirements

32. Window Size & Openable Area

M, Meets Minimum Requirements

33. Window & Door Condition/Mechanical Venting

M, Meets Minimum Requirements

34. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

35. Plumbing Fixtures

M, Meets Minimum Requirements

36. Water Flow

RRE, Repair/Replace: - Unable to properly test, the water is shut off. Reinspection required. (RRE)

37. Gas Piping

M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Dining Room/Living Room

- 38. Walls and Ceiling Components
M, Meets Minimum Requirements
- 39. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 40. Floor Area & Ceiling Height
M, Meets Minimum Requirements
- 41. Floor Condition
M, Meets Minimum Requirements
- 42. Window Size & Openable Area
M, Meets Minimum Requirements
- 43. Window & Door Condition
B, Below Minimum Requirements: - Missing/damaged window components. (B)
- 44. Electrical Outlets/Fixtures
SC, Suggested Correction: - Missing cover plates. (SC)

Bathroom ((Lower level))

- 45. Walls & Ceiling Components
M, Meets Minimum Requirements
- 46. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 47. Floor Condition
M, Meets Minimum Requirements
- 48. Window Size & Openable Area/Mechanical Vent
M, Meets Minimum Requirements
- 49. Window & Door Condition
M, Meets Minimum Requirements
- 50. Electrical Outlets & Fixtures
SC, Suggested Correction: - Missing plate(s). (SC)
- 51. Plumbing Fixtures
M, Meets Minimum Requirements
- 52. Water Flow
RRE, Repair/Replace: - Water off at time of evaluation. Re-inspection required. (RRE)

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Bathroom ((upper level))

45. Walls & Ceiling Components

B, Below Minimum Requirements: - Damaged areas. (B)

46. Evidence of Dampness or Staining

M, Meets Minimum Requirements

47. Floor Condition

M, Meets Minimum Requirements

48. Window Size & Openable Area/Mechanical Vent

M, Meets Minimum Requirements

49. Window & Door Condition

M, Meets Minimum Requirements

50. Electrical Outlets & Fixtures

SC, Suggested Correction: - Missing plate(s). (SC)

51. Plumbing Fixtures

M, Meets Minimum Requirements

52. Water Flow

RRE, Repair/Replace: - Water off at time of evaluation. Re-inspection required. (RRE)

Hallways/Stairwells

53. Walls and Ceiling Components

M, Meets Minimum Requirements

54. Evidence of Dampness or Staining

M, Meets Minimum Requirements

55. Floor Condition

M, Meets Minimum Requirements

56. Window & Door Condition

M, Meets Minimum Requirements

57. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

58. Stairs and Railings

M, Meets Minimum Requirements

59. Smoke Detectors /CO Detectors

M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required		RRP :=Repair/Replace, Permit/City Inspector Required		LIC :=Safety Check, Licensed Contractor Required

Bedroom ((Lower, SW))

- 60. Walls and Ceiling Components
 - B, Below Minimum Requirements: - Damaged areas. (B)
- 61. Evidence of Dampness or Staining
 - M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
 - M, Meets Minimum Requirements
- 63. Floor Condition
 - M, Meets Minimum Requirements
- 64. Window Size & Openable Area
 - M, Meets Minimum Requirements
- 65. Window & Door Condition
 - B, Below Minimum Requirements: - Missing/damaged window components. (B)
- 66. Electrical Outlets/Fixtures
 - SC, Suggested Correction: - Missing cover plates. (SC)

Bedroom ((lower, SE))

- 60. Walls and Ceiling Components
 - B, Below Minimum Requirements: - Damaged areas. (B)
- 61. Evidence of Dampness or Staining
 - M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
 - M, Meets Minimum Requirements
- 63. Floor Condition
 - M, Meets Minimum Requirements
- 64. Window Size & Openable Area
 - M, Meets Minimum Requirements
- 65. Window & Door Condition
 - B, Below Minimum Requirements: - Missing/damaged window components. (B)
- 66. Electrical Outlets/Fixtures
 - SC, Suggested Correction: - Missing cover plates. (SC)

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required		RRP :=Repair/Replace, Permit/City Inspector Required		LIC :=Safety Check, Licensed Contractor Required

Bedroom ((upper, SW))

- 60. Walls and Ceiling Components
 - B, Below Minimum Requirements: - Damaged areas. (B)
- 61. Evidence of Dampness or Staining
 - M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
 - M, Meets Minimum Requirements
- 63. Floor Condition
 - M, Meets Minimum Requirements
- 64. Window Size & Openable Area
 - M, Meets Minimum Requirements
- 65. Window & Door Condition
 - B, Below Minimum Requirements: - Missing/damaged window components. (B)
- 66. Electrical Outlets/Fixtures
 - SC, Suggested Correction: - Missing cover plates. (SC)

Bedroom ((upper, SE))

- 60. Walls and Ceiling Components
 - B, Below Minimum Requirements: - Damaged areas. (B)
- 61. Evidence of Dampness or Staining
 - M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height
 - M, Meets Minimum Requirements
- 63. Floor Condition
 - M, Meets Minimum Requirements
- 64. Window Size & Openable Area
 - M, Meets Minimum Requirements
- 65. Window & Door Condition
 - B, Below Minimum Requirements: - Missing/damaged window components. (B)
- 66. Electrical Outlets/Fixtures
 - SC, Suggested Correction: - Missing cover plates. (SC)

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Porch/Sunroom/Other

- 67. Walls and Ceiling Components
NA, Not Applicable/Does Not Apply
- 68. Evidence of Dampness or Staining
NA, Not Applicable/Does Not Apply
- 69. Floor Condition, Area & Ceiling Height
NA, Not Applicable/Does Not Apply
- 70. Window & Door Condition
NA, Not Applicable/Does Not Apply
- 71. Electrical Outlets/Fixtures
NA, Not Applicable/Does Not Apply

Attic Space

InsulationType:Fiberglass

InsulationDepth:6-9

- 72. Roof Boards & Rafters / Ventilation
M, Meets Minimum Requirements
- 73. Evidence of Dampness or Staining
M, Meets Minimum Requirements
- 74. Electrical Outlets & Fixtures
M, Meets Minimum Requirements
- 75. Mechanical Venting
M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required		RRP :=Repair/Replace, Permit/City Inspector Required		LIC :=Safety Check, Licensed Contractor Required

Exterior

76. Foundation

M, Meets Minimum Requirements

77. Basement Windows

B, Below Minimum Requirements: - Damaged screens. (B)
Weathered window. (B)

78. Drainage (Grade) / Rainleaders

B, Below Minimum Requirements: - Deteriorated gutter(s). (B)
Grade in areas does not allow surface water to drain away from building. (B)

79. Exterior Walls

B, Below Minimum Requirements: - Weathered/damaged siding. (B)
Some rot & decay noted. (B)

80. Doors (frames/storms/screens/deadbolt locks)

B, Below Minimum Requirements:

81. Windows (frames/storms/screens)

B, Below Minimum Requirements: - Weathered wood components. (B)
Fogged glass indicates broken thermal seal on door/window(s). (B)

82. Stoops

M, Meets Minimum Requirements

83. Cornice & Trim

M, Meets Minimum Requirements

84. Roof Covering & Flashing

M, Meets Minimum Requirements

85. Chimney

M, Meets Minimum Requirements

86. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

87. Exterior Plumbing-Backflow Prevention

M, Meets Minimum Requirements

88. Two-Family Dwelling Egress

NA, Not Applicable/Does Not Apply

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements	C :=Comments	NA :=Not Applicable/Does Not Apply	B :=Below Minimum Requirements	SC :=Suggested Correction
RRE :=Repair/Replace, Evaluator Verification Required	RRP :=Repair/Replace, Permit/City Inspector Required	LIC :=Safety Check, Licensed Contractor Required		

Open/Unheated Porch

89. Floors

SC, Suggested Correction: - Potential for structural failure of floor system. (SC)

90. Walls

M, Meets Minimum Requirements

91. Roof/Ceiling

M, Meets Minimum Requirements

92. Doors/Screens/Windows

NA, Not Applicable/Does Not Apply

93. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Garage

94. Roof Structure & Covering

M, Meets Minimum Requirements

95. Wall Structure & Covering

M, Meets Minimum Requirements

96. Garage Doors

M, Meets Minimum Requirements

97. Automatic Garage Door Opener

M, Meets Minimum Requirements

98. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Miscellaneous

99. Clutter/Sanitation/Vermin

M, Meets Minimum Requirements

100. Other

M, Meets Minimum Requirements

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



Truth in Housing Repair Notification

City of Minneapolis-Inspections Division

Truth in Sale of Housing, 250 South 4th Street, Room 300
Minneapolis, MN 55415

Issued To:

3/29/2010

Wachovia Mortgage c/oSteve
Mikula
11660 Theater Dr N #110
Champlin, MN 55316

Owner does not have to complete repairs if the house is not sold.

Pursuant to Minneapolis Code of Ordinances, Sections 248.20 and 248.225, the owner may make the repairs. If the owner makes the repairs, a Certificate of Approval (needed for closing) will be issued after the repairs have been inspected and approved. The owner does not have to complete the repairs if the house does not sell. If the owner does not make the repairs, the buyer must sign an acknowledgement of responsibility form (provided by the City) and return it to the City. The buyer has 90 days from closing to complete the repairs. Your prompt cooperation in attending to the repair items is appreciated however, failure to comply by these deadlines may result in legal action.

REQUIRED REPAIRS

ID	Description	Area	Comment
9	Sump Pumps	Basement	Repair/Replace: - Loose cover on sump pump. (RRE)
10	Smoke Detectors / CO Detectors	Basement	Repair/Replace: - Does not respond when tested. (RRE)
16	Drain, Waste & Vent Piping	Plumbing	Repair/Replace: - Water off at time of evaluation. Re-inspection required. (RRE)
17	Water Supply Piping	Plumbing	Repair/Replace: - Water off at time of evaluation. No other visible problems. Evaluator required to return after water service restored. (RRE)
20	Water Heater & Installation	Water heater	Repair/Replace: - Missing/improper T&P relief valve discharge pipe. Pipe must be full sized, of proper metal materials, not capped, must extend to within 18" of the floor, with no threads on end of the pipe. (RRE)
21	Water Heater Venting	Water heater	Repair/Replace: - Water heater venting not viewed in operation. Reinspection required (RRE)
22	Heating Plant Viewed in Operation	Heating	Repair/Replace: - Heating plant not in operation. Reinspection required. (RRE)
28	Plumbing Fixtures	Laundry	Repair/Replace: - Water off at time of evaluation. No other visible problems. Evaluator required to return after water service restored. (RRE)
36	Water Flow	Kitchen	Repair/Replace: - Unable to properly test, the water is shut off. Reinspection required. (RRE)
52	Water Flow	Bathroom((Lower level))	Repair/Replace: - Water off at time of evaluation. Re-inspection required. (RRE)
52	Water Flow	Bathroom((upper level))	Repair/Replace: - Water off at time of evaluation. Re-inspection required. (RRE)

SAFETY CHECKS

The systems listed below must be checked by a licensed contractor. The contractor must be licensed by the City of Minneapolis and/or the State of Minnesota in that specific trade to check the work. Return safety check forms to the address above or fax to (612) 673-2437. If "Evaluator Return" is indicated below, the evaluator may return to view the system that was not in operation at the time of the initial evaluation. The evaluator may find additional work is needed on the system.

Truth in Sale of Housing Disclosure Report

Address: 4937 6th St N Minneapolis, MN



If the system was repaired or replaced, only a licensed contractor (not the evaluator) can do the safety check. Permits may be needed.

NONE

PERMIT REQUIRED REPAIR

The permit must be pulled before scheduling. Call the inspector listed on the permit to set an appointment. You need to have the permit number to set the appointment. There will be a charge for the permit, which covers the inspection.

NONE

Reinspection Process

When all the items are completed they must be inspected and approved.

For items that need a permit:

If your notification indicates PERMIT NEEDED, the permit(s) must be pulled and work completed BEFORE the re-inspection takes place. If you are a homeowner occupant of a single family house, you may obtain a permit, if you are not, you must hire a licensed contractor. Bring this notification with you when you apply for permits.

For items that do not need a permit:

Call the evaluator who did the initial TISH report to re-inspect all the non-permit items. The evaluator's name and phone number are on the bottom of page 1 of the report. There will be a charge for this inspection.

Appeal

This repair notice may be appealed. Section 248.150 of the Minneapolis Code of Ordinances provides that an appeal must be filed in writing within thirty (30) days of the date of this notice accompanied with a \$100 filing fee. If you wish to appeal this order, call (612) 673-5840 for an application.

Assistance

If you need financial assistance to complete these repairs, you may call the Greater Metropolitan Housing Corporation (GMHC) at 612-378-7985.